

Visual Condition Report

2018 CBI Hydra-Dec II Bale Deck

Disclaimer: This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.

General Overview

Unit appears structurally sound. Surface rust present in typical wear areas. Deck stored on blocks.

Deck Condition

Steel deck straight and solid. No major dents or deformation. Normal cosmetic wear.

Hydraulic Components

Hydraulic slide/tilt hardware appears complete. Functional hydraulic testing not performed.

Electrical

Rear wiring harness present but requires reconnection. Lights untested.

Fenders & Side Rails

Fenders Intact - However, **one tie-down rail/strap bracket is bent ** see photos

Frame & Undercarriage

Frame appears straight with normal weathering. No visible cracks.

Measurements

Deck length: 12 ft. - Deck Width: 7 ft