

## Visual Condition Report – 2005 John Deere 710G Backhoe Loader

Machine: 2005 John Deere 710G

Hours: 6,810

Location: County of Paintearth No. 18, Alberta

### Overall Condition Summary

Unit shows average wear for age and hours. Cosmetics are average in typical wear areas, major components appear intact. No major structural issues noted. Interior seat torn and cab is dirty. Pins, bushings, and cylinders show typical seepage and paint wear for age. Tires in good usable condition.

Disclaimer: This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.

### Exterior Condition

- Paint faded and scratched consistent with age
- Various dents/dings consistent with age
- Loader arms and backhoe boom show some surface rust
- 4-in-1 bucket cutting edges look good
- Rear bucket shows typical wear on teeth and edges

### Cab & Interior

- Seat cushion torn
- Controls and levers intact
- Cab glass intact, some grime/dust present
- Steering wheel, dash, and console show typical wear

### Engine Compartment

- Powered by Deere 6068T engine
- No major leaks seen
- Hoses show age-related wear

- Engine EPA tag intact and visible

#### Hydraulics

- Cylinders show paint wear and minor seepage
- Hoses worn, some cracking visible on outer jackets
- Extenda-stick pins and bushings show visible wear but operational
- Rear thumb and linkage intact

#### Tires

##### Front Tires – 15x19.5

- Brand: Galaxy
- Condition: Approx. 40–50% tread remaining

##### Rear Tires – 21L-28

- Brand: Firestone
- Condition: Approx. 50–60% tread remaining

#### Attachments & Features

- 4-in-1 front bucket – 8 ft wide
- 3 ft rear dig bucket
- Hydraulic rear thumb
- Extenda-stick boom
- 4WD
- Enclosed cab

#### Notable Observations

- Cosmetic condition average
- Seat cover requires replacement
- Hydraulics show typical wear but appear complete and functional

