

Visual Condition Report 2008 Komatsu D65WX-15E0

Dozer with Ripper

General Condition:

Machine presents in good working condition for its age. Cosmetics show significant wear, scratches, and paint fade consistent with age. Panels secure. No major structural damage observed.

Engine Compartment:

Komatsu SAA6D140E-5 engine. Engine reportedly rebuilt approx. 2,500 hours ago (not verified). No visible active leaks at time of inspection. Hoses and lines worn but intact.

Undercarriage:

Undercarriage is new: pads, rails, idlers, rollers, and sprockets replaced recently.

Blade & Hydraulics:

Blade face worn but functional. Cutting edges have standard wear. Lift and tilt cylinders dry with minor seepage at some fittings. Pins/bushings show moderate play consistent with age.

Ripper:

Single shank ripper in good working condition. Cylinder dry. Hinge and mounting points show moderate wear.

Cab & Controls:

Cab interior worn, seat fabric intact. Controls functional. HVAC present; functionality not verified. Gauges readable. Some switches and plastics show age-related wear.

Other Notes:

EPA label present. Machine starts, runs, moves, and operates very well.

Disclaimer:

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.