

# Visual Condition Report

## 2019 Western Star 4900 Triaxle Day Cab Truck

Location:	Near Calgary, AB
Engine:	Cummins X15 505 Diesel Engine (505 hp)
Transmission:	Eaton Fuller 18-Speed Manual
Odometer:	567,097 km (335,284 mi)
Engine Hours:	14,284 hrs
GVWR:	71,000 lb (32,205 kg)
Axle Ratio:	4.10
Wheelbase:	289 in
Front Tires:	385/65R22.5 Goodyear
Rear Tires:	11R24.5 Goodyear

### ***Condition Summary:***

- Cab interior is clean and functional, showing moderate wear on driver's seat and minor scuffs on flooring.
- All gauges, switches, and controls appear intact with no major cracks or damage to dash components.
- Exterior body panels are straight with typical cosmetic wear; paint in overall good condition with some rock chips on lower fenders.
- Frame rails are structurally solid, showing localized surface rust and previous equipment mount hole marks.
- Cummins X15 engine appears clean with no visible oil or coolant leaks; tag confirms manufacture date of April 2018.
- Transmission: Eaton Fuller 18-speed shifts through all gears
- Front steer tires show moderate wear with outer edge rounding; rear tires approximately 60–70% remaining tread depth.
- Suspension and air bags visually intact, showing no cracks or leaks during static inspection.
- Brake components show typical service wear; no visible air line leaks or damaged chambers.
- Electrical and lighting harnesses appear intact; no frayed wires observed along frame rail.
- Equipped with full locking differentials and Webasto engine pre-heater; operational condition not tested.
- CVIP inspection has expired; will require re-certification prior to road use.

- Unit presents as a solid, well-spec'd tridem day cab truck suitable for vocational or highway applications.

Disclaimer: This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.