

# Visual Condition Report

## 2013 Caterpillar 950K Wheel Loader with Bucket

Location: Near Calgary, AB

232 hp - Cat C7.1 ACERT Diesel Engine

Operating Weight: 42,811 lb (19,425 kg)

Hours: 29,054

Tire Size: 23.5R25 Goodyear L3 Radials

Bucket Width: 9'7" (WBM General Purpose)

A/C & Heat

Powershift Transmission

Loadrite L-Series 2180 Scale System Installed EPA

Label Present

Made in the USA

S/N Prefix: CAT0950K

Emission Family: DPRXL07.01B1 (EPA 2013 Tier 4i)

Component	Condition / Comments
Cab / Interior	Seat upholstery in good condition. Front windshield needs replacement
Exterior / Paint	Paint in good overall condition with minor wear consistent with use.
Engine	CAT C7.1 engine starts and runs well. No visible leaks.
Transmission	Powershift transmission operational at time of inspection.
Tires	Goodyear 23.5R25 L3 tires – even wear, good tread depth remaining.
Hydraulics	No visible leaks. Smooth bucket and lift operation.
Bucket	9'7" WBM general-purpose bucket. Cutting edge solid, no major weld repairs.
Electrical	All major functions operational. Lights and switches appear functional.

**Disclaimer:** This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.