

VISUAL CONDITION REPORT

Machine: Caterpillar RC60 Rough Terrain Forklift

Serial Number: 31A01*** **Model Year:** 1983 min - 1989 max

Hours: 8,094

Tires: Front: 385/65R22.5 • Rear: 12x16.5 (Front tires equipped with chains)

Location: Cranbrook, BC Area

General Condition

Overall, the forklift presents as a solid, older machine showing normal wear consistent with age and use. Paint is faded and scratched, with areas of surface rust visible around fenders and counterweight. Structural components appear intact with no visible cracks or major weld repairs. Machine has been stored outdoors.

Powertrain

Engine compartment closed during inspection; no visible leaks noted externally. Starts and runs (as observed in operation photo). Exhaust stack and muffler intact with surface rust. Appears to be powered by a diesel engine (Caterpillar or Perkins variant typical of RC60 models).

Mast & Forks

Dual-stage mast appears straight and operational. Forks show heavy surface rust and wear consistent with use but no visible bends or cracks. Lift and tilt cylinders show signs of age; no active leaks observed in photos. Chains and rollers appear serviceable.

Hydraulics

No major oil residue visible on external hydraulic lines. Control levers intact and functional. Hydraulic operation observed (mast raised and lowered).

Operator Station

Seat and steering wheel worn from use. Levers, pedals, and gauges appear original. Hour meter lens yellowed but readable (shows 8,094 hrs). Safety cage structure intact. Fire extinguisher mounted behind operator seat.

Tires

Front and rear tires: Fronts fitted with heavy-duty traction chains; tread fair. Rear tires fair with moderate wear; no visible damage to rims.

Lighting & Safety

Work lights mounted; condition fair. ROPS canopy intact. No visible seatbelt (confirm presence if required for compliance).

Overall Assessment

Machine is in fair running condition for age, with typical cosmetic wear. Operational with functioning mast and steering. Suitable for yard or rough-terrain lifting applications where appearance is not critical.

Disclaimer: *This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.*