

Visual Condition Report

1975 John Deere 2130 Tractor with

Loader • 2WD Loader: John Deere E0146

Loader with Bucket: 5ft

Overall Condition:

- Tractor presents in fair / good usable condition for its age.
- Paint is faded with surface rust, scrapes, and weathering throughout.
- Panels appear straight with no major impact damage visible.
- Loader shows typical wear but appears structurally sound.

Engine Bay

- Engine appears complete; typical wear, paint flaking, and grime for age.
- Hoses show weathering but appear intact.
- No major leaks visible in photos, but some moisture/oil residue present.
- Starter and fuel system show some cosmetic corrosion.
- Exhaust stack straight.

Hydraulics

- Loader cylinders: cosmetic weathering; normal seepage at fittings.
- 3-Point Hitch: arms intact with rust present.
- Rear remote: couplers aged.

Transmission & Controls

- Hi-Lo powershift and gear selector levers present.
- Controls show scraping and fading.
- Pedals worn but intact.
- Seat padding cracked.

Tires

Front Tires – 7.5-16

- Moderate tread depth

Rear Tires – 18.4-30

- Good tread depth

Loader & Bucket

- Loader frame straight with scratches and paint loss.
- Bucket: 5 ft (60 inches).
- Cutting edge worn.

Rear End & PTO

- PTO shaft present; housing weathered.
PTO always stays on and does not disengage
- Rear linkage complete; rust on stabilizers.
- Lights present.

Other Notes

- German-built model.
- Hour meter shows 183; true hours unknown.

Disclaimer

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.

