

# Visual Condition Report

<b>Make:</b>	John Deere
<b>Model:</b>	5100M
<b>Year:</b>	2016
<b>Hours:</b>	2,770
<b>Drive:</b>	4WD
<b>Engine:</b>	John Deere 4045HLV70, 4.5L Diesel, 104 kW (140 hp) @ 2200 rpm EU-EPA
<b>Transmission:</b>	PowerReverser
<b>PTO:</b>	540 / 540E
<b>Front Tire Size:</b>	13.6R24
<b>Rear Tire Size:</b>	480/70R34
<b>Operating Weight:</b>	8,750 lbs (approx)
<b>Serial Number:</b>	1LV5100MKGG5*****
<b>Condition:</b>	Excellent overall — clean paint, glass, and cab interior with minimal wear.

**Disclaimer:**

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.