

Visual Condition Report

Make:	John Deere
Model:	5100R
Year:	2013
Hours:	3,224
Drive:	4WD
Engine:	John Deere 4045HL284, 4.5L Diesel
Transmission:	PowerReverser
PTO:	540 / 540E
Front Tire Size:	380/70R24
Rear Tire Size:	480/70R34
Operating Weight:	8,750 lbs
Serial Number:	1L05100RHDJ778484
Condition:	Excellent overall — clean paint, glass, and interior; minimal tire wear.

Disclaimer:

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.