

Visual Inspection Report

2006 Sterling L9500 Triaxle Tank Truck – 22,000L • DOT407SS Aluminum Tank

VIN: 2FWRAZCK16A*****

Location: County of Newell, AB

Engine: 515 hp • Detroit Diesel Series 60 • EPA Label Present

Configuration: Triaxle Tank Truck

GVW: 42,000 kg • **Tare:** 17,000 kg

GVWR: 33,430 kg • **GAWR Front:** 9,072 kg • **GAWR Rear:** 8,119 kg ×3

Tires: Front 425/65R22.5 • Rear 11R24.5

Odometer: 347,508 km

Hours: 17,653

CVIP: Good until April 2026

Transmission: Eaton Fuller 18 Speed Manual

Tank: DOT407SS Stainless Steel • Dual Compartments (16,000 L & 6,000 L)

Tank Inspection: Completed Nov 2025

Condition Summary

Exterior & Body

Paint wear, scuffs, and surface rust consistent with age. No major cab or frame structural damage observed.

Tank & Structure

Tremcar DOT407SS Stainless Steel tank is structurally sound with typical cosmetic wear; walkway, ladder, and mounting points intact.

Pump Box & Plumbing

Pump compartment stained from petroleum use. Components intact; meters operational; valves aged but functional.

Tires & Wheels

Front tires approx. 50–60% tread; rears 40–60%. Rims show corrosion but no visible structural cracks.

Interior

Dashboard complete; moderate wear on steering wheel. Seat covers installed; overall interior functional.

Engine & Driveline

Detroit Series 60 shows typical wear. No major leaks visible. Intake piping appears newer; belts and turbo intact.

Frame & Undercarriage

Surface rust present; no visible structural defects. Rear bumper shows corrosion.

Disclaimer: This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.

