

VISUAL INSPECTION REPORT

2012 Peterbilt 365 Knuckle Boom Truck – Hiab 166 B-3 CLX

Location: Calgary, AB

ENGINE & DRIVETRAIN

Cummins ISL9 370 HP diesel engine.

Over \$25,000 spent on a recent engine rebuild (p.

Eaton Fuller 13-speed manual transmission. Tandem rear axles with lockers. Positive air shutoff installed.

BOOM / CRANE

Hiab 166 B-3 CLX knuckle boom. Approx. 4,900 kg @ 3.1 m. Max reach 10.3 m. Max lift height 12.8 m.

Boom structure appears straight with no visible cracks or weld repairs observed.

CHASSIS & DECK

Peterbilt 365 vocational frame. 18 ft x 8'3" flat deck. Frame rails appear straight with no visible structural damage.

TIRES

Front: 385/65R22.5 | Rear: 11R24.5. Tires appear in good visual condition.

METERS

475,370 km | 14,341 hours

OVERALL CONDITION

Good commercial condition. Suitable for immediate work subject to buyer inspection.

DISCLAIMER

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance.

Buyers are encouraged to perform their own independent inspection prior to purchase.

