

VISUAL CONDITION REPORT

2013 John Deere 5100M Tractor

Manufacturer	John Deere
Model	5100M
Year	2013
Serial Number	1LV5100MLDV1*****
Hours	3,500 hrs
Engine	John Deere 4045HLV70, 4.5L Diesel, 100 HP
Drive	4WD
Transmission	PowerReverser 16F/16R
PTO	540 / 540E
Rear 3-Point Hitch	Category II
Rear Hydraulics	Dual Remotes
Cab	Enclosed with Heat & A/C
Front Tire Size	340/85R24 – Excellent Condition
Rear Tire Size	420/85R34 – Excellent Condition
Operating Weight	8,750 lbs

Overall Condition:

Good overall condition. Clean cab and exterior. Minor surface wear consistent with age. Engine starts and runs strong with no visible leaks. Hydraulics tight and fully functional. Tires in excellent condition with deep tread remaining. Unit appears work-ready.

Disclaimer:

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.