

# Visual Condition Report

**Equipment:** 2018 John Deere 872G Motor Grader • SN#: 1DW872GPCJF\*\*\*\*\*

**Engine:** John Deere PowerTech 9.0L Diesel Engine - US EPA Compliant

**Horsepower:** 280 hp (Net) • Hours: 8,641

**Operating Weight:** Approx. 44,000 lbs - Maximum Operating Weight: 55,000 lbs

**Transmission:** Direct-Drive Powershift

**Configuration:** 6WD / Rear Ripper / Snow Wing / 16ft Moldboard - Made in the USA

## Visual Condition Summary

**Cab & Controls:** Enclosed cab with surface rust along lower door frame and hinges. Glass intact. Overall cab structure solid.

**Engine Bay:** Clean and well-kept. No visible leaks. Wiring and hoses appear intact. Exhaust and DEF system show normal discoloration for age.

**Hydraulics:** Cylinders and hoses appear in fair to good condition. No visible oil seepage. Connections look tight.

**Blade & Circle:** Cutting edge worn but serviceable. Moldboard face rusted but solid. Circle gear and linkage show light wear consistent with use.

**Frame & Articulation:** Structural components intact with light surface rust. Articulation pins appear tight with minor wear.

**Rear Ripper:** Structurally sound with paint wear and oxidation typical for service life.

**Tires:** Appear in good condition with strong tread depth. No major sidewall damage visible.

**Overall Appearance:** Straight body panels, uniform wear, and consistent paint fading typical for working grader.

**Overall Condition Rating:** *Good – operational appearance with moderate cosmetic wear. Machine appears ready for work pending standard maintenance and pre-use checks.*

## **Disclaimer:**

*This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.*