

## VISUAL INSPECTION REPORT

### 2007 Komatsu D155AX-6 Dozer with Single Shank Ripper

Disclaimer: This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.

Overall Condition: Good used working dozer with typical wear. Undercarriage shows medium wear, sprockets worn (new sprocket segments included - uninstalled)

#### 1. Engine & Powertrain

- Engine appears intact with no major leaks.
- Hoses and wiring intact.
- Final drive housings intact; sprockets worn.

#### 2. Undercarriage Condition

- Sprockets: worn; new segment set included.
- Rails/chains: medium wear
- Rollers: medium wear
- Idlers: medium wear
- Pads: medium wear

#### 3. Blade Assembly

- 12 ft blade, cutting edge moderate wear.
- Cylinders show no active leaks.

#### 4. Ripper

- Single shank ripper functional.
- No visible cylinder leaks.

#### 5. Hydraulics

- No major leaks visible.
- Hoses intact.

#### 6. Cab Condition

- Seat good.
- Controls show typical wear.
- 13,313 machine hours.

#### 7. Exterior

- Typical paint wear, scratches.
- No visible structural cracks.

#### 8. Additional Equipment

- Complete new sprocket segment set included.