

# VISUAL INSPECTION SHEET

Year / Make / Model	2016 RAM 3500 Crew Cab Chassis 4x4
VIN	3C7WRTCL0GG*****
Engine	6.7L Cummins Turbo Diesel
Transmission	AISIN AS69RC 6-Speed Automatic
Odometer (Showing)	317,487 km
Engine Hours (Showing)	Idle: 2,774 hrs   Drive: 4,405 hrs
GVWR	14,000 lbs
Axle Ratio	4.10
Deck	CM Flat Deck with Wood Sideboards

Category	Visual Condition Notes
Cab / Body	Moderate to heavy corrosion on lower doors, cab corners, and rocker panels
Paint	White paint with significant rust bleed-through
Flat Deck	Heavy corrosion on steel deck and rear bumper
Tires / Wheels	Steel wheels rusted; tires mid-life
Interior	Driver seat torn; heavy work-truck wear
Lights / Glass	Lights and glass appear intact
Mechanical (Visual Only)	No visible leaks noted; no testing performed

**Disclaimer:** This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.