

## **VISUAL CONDITION REPORT**

**Unit:** 2007 Western Star 4900 Grain Truck with 16 ft Cascade Grain Box

**Location:** County of Paintearth No. 18, Alberta

### **Exterior Condition:**

- Cab paint shows typical wear, fading, and minor chips for age.
- Grain box shows surface rust spots, scuffs, and wear on rear door hardware.
- Tarp system present and appears functional.
- No major structural damage observed.

### **Tires:**

- Front Tires: 385/65R22.5 – Approx. 40–50% tread.
- Rear Tires: 11R22.5 – Matching set, approx. 50–60% tread, some minor outer lug wear.

### **Engine & Driveline:**

- Detroit Series 60 appears complete with no major leaks visible.
- Hoses, belts, and fittings show typical age wear.
- No visible damage to turbo or charge-air piping.

### **Interior Condition:**

- Seat upholstery shows wear but intact.
- Dash switches and gauges present; some cosmetic wear.
- Floor mat and panels show heavy-use wear.

### **Grain Box:**

- 16 ft Cascade box – inside shows surface rust typical of age and use.
- Rear swing door hardware intact with visible cosmetic rust.
- Floor appears solid with no visible holes or structural issues.
- Passenger side of the grain box has a crease/dent that has been repaired.

### **Lights & Accessories:**

- Mirrors, signals, and lighting present; not fully tested for function.

### **Disclaimer:**

This visual condition report is based solely on a visual inspection and the information provided at the time of assessment. No mechanical testing or diagnostic analysis has been performed. We do not guarantee the accuracy of hour readings, mechanical condition, or operational performance. Buyers are encouraged to perform their own independent inspection prior to purchase.